




Carmen Schäfer (Autor)

Recrystallization Modeling considering Second-Phase Particles



<https://cuvillier.de/de/shop/publications/548>

Copyright:

Cuvillier Verlag, Inhaberin Annette Jentsch-Cuvillier, Nonnenstieg 8, 37075 Göttingen, Germany

Telefon: +49 (0)551 54724-0, E-Mail: info@cuvillier.de, Website: <https://cuvillier.de>

Content

1. Introduction	1
2. Recrystallization	5
2.1 Introduction	5
2.2 Recrystallization Nucleation	6
2.2.1 Instability criteria	6
2.2.2 Types of nucleation	7
2.2.3 Influences on nucleation	11
2.3 Nucleus Growth	12
2.3.1 Grain boundary migration	12
2.3.2 Influence of recovery	13
2.3.3 Influence of small particles - Zener drag	14
2.3.4 Influence of solutes - solute drag	16
2.4 Recrystallization Models	18
2.4.1 Phenomenological models	19
2.4.2 Geometric microstructure models	21
2.4.3 Vertex models	21
2.4.4 Discrete models	22
2.4.5 Recrystallization texture models	23
3. Simulation of Recrystallization using Cellular Automata	25
3.1. Introduction	25
3.2 Fundamentals	26
3.3 Theory of the Cellular Operator for Recrystallization CORE	27
3.3.1 History of CORE	27
3.3.2 A nucleation model for CORE	28
3.3.3 Modifications of the CORE model	29
3.3.4 Theory of CORE	29
3.4 Model Input	33
3.5 Model Output	36
3.6 Coupling to the Softening Model CORE-3IVM+	37
3.7 Coupling to the Precipitation Model CORE-ClaNG	42

3.8	Modifying the Real-Time Scaling	44
3.9	Quantitative Nucleation Modeling in CORE - Modifications	45
3.9.1	Nucleation – and the importance of the absolute nucleus number	46
3.9.2	Nucleation at grain boundaries	47
3.9.3	Nucleation in orientation gradients	48
3.9.4	Influence of Zener drag on nucleation	50
3.9.5	The total nucleus number	51
4.	Parameter Studies	55
4.1	Introduction	55
4.2	Influence on Recrystallization Texture	55
4.2.1	Influence of pre-deformation texture	56
4.2.2	Influence of dislocation density on growth	58
4.2.3	Influence of strain	59
4.2.4	Influence of alloy composition	62
4.2.5	Influence of particle-stimulated nucleation	64
4.2.6	Influence of Zener drag	64
4.2.7	Influence of the arrangement in GIA-Aggregates	65
4.3	Influence on Recrystallization Kinetics	66
4.3.1	Comparison with JMAK Theory	66
4.3.2	Influence of the number of nuclei	67
4.3.3	Influence of the shape of the deformed grains	68
4.3.4	Influence of the nucleation rate	69
4.3.5	Influence of dislocation density on growth	69
4.3.6	Influence of strain	70
4.3.7	Influence of inhomogeneities during growth	71
4.3.8	Influence of mobility on growth	74
4.3.9	Influence of Zener drag	76
4.3.10	Influence of heating rates	80
4.3.11	Influence of particle-stimulated nucleation	83
4.3.12	Influence of solute drag	84
4.4	Influence on Grain Size Distribution	86
4.4.1	Influence of the nucleus number	86
4.4.2	Influence of strain	89
4.4.3	Influence of inhomogeneities	90
4.4.4	Influence of mobility distribution	92
4.4.5	Influence of particle-stimulated nucleation	92
4.4.6	Influence of Zener drag	94

4.5	Precision and Errors	95
4.5.1	Input parameters	95
4.5.2	Inaccuracies during the simulation	96
4.5.3	Evaluation & Interpretation	97
4.6	Classification of Effects on Recrystallization	98
5.	Model for Particle-Stimulated Nucleation	101
5.1	Introduction	101
5.2	Evolution of the Deformation Zone (fcc) – Experiments	101
5.2.1	Appearance of the deformation zone	101
5.2.2	Subgrain size	103
5.2.3	Microtexture in the deformation zone	105
5.2.4	P- and 22° ND rotated Cube texture component	108
5.2.5	Nucleus texture and frequency	109
5.3	The GIA-DZ model for In-Grain Deformation Zone Evolution	111
5.3.1	Model Setup and general model behavior	111
5.3.2	FEM modeling	113
5.3.3	Strain evolution in the particle vicinity	113
5.3.4	Texture evolution in the particle vicinity	115
5.3.5	Texture evolution in ideal orientations	119
5.4	Modeling the Evolution of the Deformation Zone (fcc)	121
5.4.1	Influence of deformation degree, temperature and initial texture	121
5.4.2	Comparison to experiments	123
5.5	A nucleation Model for Particle-Stimulated Nucleation	125
5.5.1	Implementation of particle-stimulated nucleation	125
5.5.2	Precipitation free zone	126
5.6	Conclusions	128
6.	Influence of Recovery on Recrystallization	129
6.1.	Introduction	129
6.2	Appearance of Recovery accompanying Recrystallization	130
6.2.1	Temperature dependence of recovery	130
6.2.2	Orientation dependence of recovery	131
6.2.3	Effect of recovery on recrystallization growth	131
6.2.4	Comparison to empirical approaches for recovery	134
6.3	Modeling Incubation Times	135
6.3.1	Two models for incubation times	136

6.3.2	Application of the incubation time criterion	137
6.3.3	Modeling nucleation rates	139
6.4	Conclusions	140
7	Recrystallization Behavior influenced by Precipitation Effects	143
7.1	Introduction	143
7.2	Experimental Data and Evaluation	144
7.2.1	Homogenization treatment for initial material	144
7.2.2	Cold rolling of the homogenized material	144
7.2.3	Characterization of the heat treated material	145
7.2.4	Data for recrystallization kinetics	147
7.2.5	Precipitation during annealing	149
7.3	Input for Recrystallization Modeling	149
7.3.1	Deformation simulations	149
7.3.2	Sub-structural quantities and nucleation	150
7.3.3	Precipitation behavior	152
7.3.4	Growth and recovery parameters	153
7.4	Results of the Recrystallization Predictions	154
7.4.1	Simulated grain size and grain size distributions	154
7.4.2	Simulated recrystallization textures	156
7.4.3	Simulated recrystallization kinetics	157
7.5	Discussion of Recrystallization Kinetics	158
7.5.1	The influence of recovery	159
7.5.2	Accuracy of ClaNG predictions	159
7.5.3	Particle coarsening	160
7.5.4	Concurrent progress of precipitation coarsening and recovery	161
7.5.5	Introducing a new kinetics	162
7.6	Conclusions	166
8	Influence of Heating Rates on the Recrystallization Behavior	169
8.1	Introduction	169
8.2	Experimental Data	170
8.2.1	Characterization of the industrially processed material	170
8.2.2	Considered time-temperature curves	171
8.2.3	Characterization of the heat-treated material	172
8.2.4	Data for recrystallization kinetics	173
8.2.5	Precipitation during annealing	174
8.2.6	Growth selection of P-oriented nuclei	175

8.3	Input for Recrystallization Modeling	177
8.3.1	Deformation Modeling	178
8.3.2	Sub-structural quantities and nucleus orientations	178
8.3.3	Precipitation input	180
8.4	Recrystallization Simulations	183
8.4.1	Recrystallization textures	183
8.4.2	Recrystallization kinetics	185
8.4.3	Grain size distribution	187
8.5	Effect of Orientation Dependent Growth Rates	190
8.6	Conclusions	191
9.	Through-Process Modeling of AA3103 Sheet Fabrication	193
9.1	Introduction	193
9.1.1	Process description	193
9.1.2	Modeling setup	194
9.2	Work-hardening Behavior	195
9.3	Hot Rolling	197
9.4	Coil Cooling	201
9.5	Cold Rolling	202
9.6	Final Annealing	205
9.6.1	Precipitation modeling	205
9.6.2	Modeling of recovery	209
9.6.3	Modeling of recrystallization kinetics	209
9.6.4	Modeling of recrystallized grain sizes	212
9.6.5	Modeling of recrystallization textures	215
9.7	Assessment of through-process predictions	219
10.	Summary	221
11.	Zusammenfassung	225
	References	229
	Curriculum Vitae	