



Maria Bostenaru Dan (Autor)
Assessment of structural performance of retrofit measures on characteristic "interwar" structures in Bucharest, Romania

Maria Bostenaru Dan

Assessment of structural performance of retrofit measures on characteristic „interwar“ structures in Bucharest, Romania

Typical log file output

Time	Step	Value	Unit	Ref.	Code	Descr.
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
13.0000	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000

Log-file imported in MS Access®

ObjectID	Object	Value	Unit	Ref.	Code	Descr.
1	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
2	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
3	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
4	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
5	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
6	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
7	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
8	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
9	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
10	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000

Log-file output imported in MS Excel®

ObjectID	Object	Value	Unit	Ref.	Code	Descr.
1	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
2	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
3	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
4	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
5	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
6	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
7	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
8	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
9	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
10	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000

MS Access® query

Cuvillier Verlag Göttingen
Internationaler wissenschaftlicher Fachverlag

<https://cuvillier.de/de/shop/publications/567>

Copyright:
Cuvillier Verlag, Inhaberin Annette Jentzsch-Cuvillier, Nonnenstieg 8, 37075 Göttingen,
Germany
Telefon: +49 (0)551 54724-0, E-Mail: info@cuvillier.de, Website: <https://cuvillier.de>

TABLE OF CONTENTS

ABSTRACT.....	iii
ACKNOWLEDGEMENTS.....	v
TABLE OF CONTENTS	vii
LIST OF FIGURES.....	xi
LIST OF TABLES	xxvii
1. INTRODUCTION.....	1
2. OUTLINE OF THIS WORK.....	3
3. HISTORY OF RETROFIT MEASURES ON MID-XXTH CENTURY BUILDINGS IN ROMANIA	4
4. DESCRIPTION OF RETROFIT MEASURES	14
4.1 MODEL “GREGOR”.....	14
4.2 MODEL “OZZI”.....	19
4.3 MODEL “CALDERON”	24
4.4 MODEL “EMINESCU”	28
4.5 MODEL “INTERBELIC”	30
5. MODELLING.....	32
5.1 SIMPLE MODELS.....	32
5.1.1 A frame.....	32
5.1.2 A column	41

5.2	REGULAR STRUCTURE MODELS	44
5.2.1	Model “Gregor”	44
5.2.2	Model “Oezzi”	48
5.3	REAL BUILDING MODEL	52
5.4	IRREGULAR STRUCTURE MODELS	53
5.4.1	Model “Eminescu”	55
5.4.2	Model “Calderon”	57
5.5	FINE GRID AND COARSE GRID	60
6.	APPLIED LOADING	79
7.	RESULTS	87
7.1	PUSHOVER ANALYSIS	88
7.1.1	Simple models	88
7.1.2	Complex building models	90
7.2	DYNAMIC TIME-HISTORY ANALYSIS	97
7.2.1	Displacement based interpretation	100
7.2.2	Stress-strain approach based interpretation	107
8.	RELEVANCE OF THE STUDY	142
8.1	MID-RISE BUILDINGS IN BUCHAREST	143
8.1.1	Buildings with 4 floors	143
8.1.2	Buildings with 5 floors	148
8.1.3	Buildings with 6 floors	153

8.2 HIGH-RISE BUILDINGS IN BUCHAREST	156
8.2.1 Buildings with 7 floors	156
8.2.2 Buildings with 8 floors	161
8.3 DISCUSSION	169
9. COMPARISON TO REAL DAMAGE TYPES.....	172
9.1 DAMAGE TO ELEMENTS	172
9.1.1 In the 1977 earthquake	172
9.1.2 Today	182
9.2 DAMAGES TO BUILDINGS.	183
9.2.1 Buildings with ground floor and six upper floors, corner tower.....	184
9.2.2 Buildings with ground floor and seven upper floors.....	185
9.2.3 Buildings with ground floor and eight upper floors	186
9.2.4 Buildings with ground floor and nine upper floors and corner tower	189
10. CONCLUSIONS	191
11. POSTFACE AND OUTLOOK.....	192
REFERENCES.....	193