




Maria Bostenaru Dan (Autor)  
**Housing in Bucharest, Romania**  
An Analysis of Vulnerability to Earthquakes



<https://cuvillier.de/de/shop/publications/762>

Copyright:  
Cuvillier Verlag, Inhaberin Annette Jentsch-Cuvillier, Nonnenstieg 8, 37075 Göttingen,  
Germany  
Telefon: +49 (0)551 54724-0, E-Mail: [info@cuvillier.de](mailto:info@cuvillier.de), Website: <https://cuvillier.de>

# CONTENTS

<b>Acknowledgements</b> .....	8
<b>Introduction: The built substance of Bucharest</b> .....	9
2. Site survey .....	14
<b>2.1. Mapping the impact</b> .....	15
<b>2.2. Surveyed characteristics</b> .....	16
3. Typological survey .....	18
<b>Before 1850:</b> .....	35
<b>Eclecticism:</b> .....	36
One family one storey house, also called "wagon house" (#85) .....	37
<b>General Information</b> .....	38
<b>Architectural features</b> .....	39
<b>Socio-economic issues</b> .....	41
<b>Structural features</b> .....	44
<b>Evaluation of Seismic Performance and Seismic         Vulnerability</b> .....	49
<b>Earthquake Damage Patterns</b> .....	55
<b>Building Materials and Construction Process</b> .....	56
<b>Construction Economics</b> .....	64
<b>Insurance</b> .....	66
<b>Seismic Strengthening Technologies</b> .....	66
<b>Pictures</b> .....	75
<b>Romanian Art Nouveau:</b> .....	96
A single-family, two-storey house with brick walls and timber floors (#84) .....	98
<b>General Information</b> .....	99
<b>Architectural Features</b> .....	100
<b>Socio-Economic Issues</b> .....	102
<b>Structural Features</b> .....	104
<b>Evaluation of Seismic Performance and Seismic         Vulnerability</b> .....	107
<b>Earthquake Damage Patterns</b> .....	112
<b>Building Materials and Construction Process</b> .....	112
<b>Construction Economics</b> .....	116
<b>Insurance</b> .....	116
<b>Seismic Strengthening Technologies</b> .....	116
<b>Pictures</b> .....	121
<b>Multistorey masonry house</b> .....	131
<b>General Information</b> .....	131
<b>Architectural Features</b> .....	132

<b>Socio-Economic Issues</b> .....	134
<b>Structural Features</b> .....	136
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	138
<b>Earthquake Damage Patterns</b> .....	142
<b>Building Materials and Construction Process</b> .....	143
<b>Construction Economics</b> .....	146
<b>Insurance</b> .....	146
<b>Seismic Strengthening Technologies</b> .....	146
<b>Pictures</b> .....	150
<b>Romanian Avant-Garde:</b> .....	155
Early reinforced concrete frame condominium building with masonry infill walls designed for gravity loads only (#96) ....	156
<b>General Information</b> .....	157
<b>Architectural Features</b> .....	159
<b>Socio-Economic Issues</b> .....	161
<b>Structural Features</b> .....	164
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	173
<b>Earthquake Damage Patterns</b> .....	180
<b>Building Materials and Construction Process</b> .....	183
<b>Construction economics</b> .....	198
<b>Insurance</b> .....	200
<b>Seismic Strengthening Technologies</b> .....	201
<b>Pictures</b> .....	209
Building of the Modern Movement - with commercial ground floor .....	225
<b>General Information</b> .....	227
<b>Architectural Features</b> .....	228
<b>Socio-Economic Issues</b> .....	229
<b>Structural Features</b> .....	232
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	237
<b>Earthquake Damage Patterns</b> .....	243
<b>Building Materials and Construction Process</b> .....	246
<b>Construction economics</b> .....	254
<b>Insurance</b> .....	256
<b>Seismic Strengthening Technologies</b> .....	256
<b>Pictures</b> .....	264
<b>1940-1950:</b> .....	278
Reinforced concrete frame structure with diagonal bracings and brick infill walls (#71) .....	279

<b>General Information</b> .....	280
<b>Architectural Features</b> .....	281
<b>Socio-Economic Issues</b> .....	282
<b>Structural features</b> .....	284
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	286
<b>Earthquake Damage Patterns</b> .....	290
<b>Building Materials and Construction Process</b> .....	290
<b>Construction Economics</b> .....	295
<b>Insurance</b> .....	295
<b>Seismic Strengthening Technologies</b> .....	295
<b>Pictures</b> .....	299
<b>International Style (1945-1977):</b> .....	309
Reinforced concrete cast-in situ shear wall buildings ("OD"-type, with "fagure" plan) (#78).....	310
<b>General Information</b> .....	311
<b>Architectural Features</b> .....	312
<b>Socio-Economic Issues</b> .....	313
<b>Structural Features</b> .....	315
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	318
<b>Earthquake Damage Patterns</b> .....	323
<b>Building Materials and Construction Process</b> .....	323
<b>Construction Economics</b> .....	327
<b>Insurance</b> .....	327
<b>Seismic Strengthening Technologies</b> .....	327
<b>Pictures</b> .....	331
Block of flats with 11 floors out of cast-in-situ concrete, gliding frameworks (#87).....	339
<b>General Information</b> .....	340
<b>Architectural Features</b> .....	341
<b>Socio-Economic Issues</b> .....	342
<b>Structural Features</b> .....	345
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	347
<b>Earthquake Damage Patterns</b> .....	352
<b>Building Materials and Construction Process</b> .....	353
<b>Construction Economics</b> .....	357
<b>Insurance</b> .....	358
<b>Seismic Strengthening Technologies</b> .....	358
<b>Pictures:</b> .....	362

<b>Romanian Socialist Architecture (1977-1990):</b> .....	379
Precast concrete panel apartment buildings (#83) .....	380
<b>General Information</b> .....	381
<b>Architectural Features</b> .....	382
<b>Socio-Economic Issues</b> .....	383
<b>Structural Features</b> .....	386
<b>Evaluation of Seismic Performance and Seismic</b>	
<b>Vulnerability</b> .....	389
<b>Earthquake Damage Patterns</b> .....	393
<b>Building Materials and Construction Process</b> .....	394
<b>Construction Economics</b> .....	397
<b>Insurance</b> .....	397
<b>Seismic Strengthening Technologies</b> .....	397
<b>Pictures:</b> .....	399
<b>Contemporary styles:</b> .....	405
Medium/high rise moment resisting reinforced concrete frame	
buildings (#97).....	406
<b>General Information</b> .....	406
<b>Architectural Features</b> .....	407
<b>Socio-Economic Issues</b> .....	409
<b>Structural Features</b> .....	411
<b>Evaluation of Seismic Performance and Seismic</b>	
<b>Vulnerability</b> .....	413
<b>Earthquake Damage Patterns</b> .....	418
<b>Building Materials and Construction Process</b> .....	419
<b>Construction Economics</b> .....	423
<b>Insurance</b> .....	424
<b>Seismic Strengthening Technologies</b> .....	424
<b>Pictures:</b> .....	427
<b>CV</b> .....	450